

Schedule

Model	BSI Review Date	Description
90 x 35 LVL E12 F14	01/08/2022	90 x 35 Spruce Structural Laminated Veneer Lumber Edge: E 12014 MPa, <i>f</i> 'b 55 MPa, <i>f</i> 's 4.0 MPa, <i>f</i> 'p 8.7 MPa Flat: E 12046 MPa, <i>f</i> 'b 54.7 MPa, <i>f</i> 's 4.4 MPa, <i>f</i> 'p 4.0 MPa Axial: <i>f</i> 't 32.7 MPa, <i>f</i> 'c 34.0 MPa F14 A-Bond E ₀ H2s 59
90 x 45 LVL E12 F14	01/08/2022	90 x 45 Spruce Structural Laminated Veneer Lumber Edge: E 12808 MPa, <i>f</i> 'b 60.9 MPa, <i>f</i> 's 4.1 MPa, <i>f</i> 'p 7.7 MPa Flat: E 13323 MPa, <i>f</i> 'b 59.8 MPa, <i>f</i> 's 4.3 MPa, <i>f</i> 'p 4.1 MPa Axial: <i>f</i> 't 31.2 MPa, <i>f</i> 'c 31.5 MPa F14 A-Bond E ₀ H2s 59
70/90/120/ 140/150/ 170/190 x 35 LVL E16 F22	01/08/2022	Various x 35 Larch Structural Laminated Veneer Lumber Edge 70: E 16194 MPa, <i>f</i> 'b 78.1 MPa, <i>f</i> 's 7.4 MPa, <i>f</i> 'p 10.9 MPa Edge 120: E 16172 MPa, <i>f</i> 'b 65.2 MPa, <i>f</i> 's 5.4 MPa, <i>f</i> 'p 10.9 MPa Edge 190: E 17025 MPa, <i>f</i> 'b 70.8 MPa, <i>f</i> 's 5.5 MPa, <i>f</i> 'p 10.9 MPa Flat: E 16211 MPa, <i>f</i> 'b 74.2 MPa, <i>f</i> 's 6.5 MPa, <i>f</i> 'p 8.7 MPa Axial: <i>f</i> 't 43.4 MPa, <i>f</i> 'c 48.6 MPa F22 A-Bond E ₀ H2s 59
90/120/140/150/ 170/190/200/240/ 290/300 x 45 LVL E14 F17	01/08/2022	Various x 45 Larch Structural Laminated Veneer Lumber Edge 90: E 15109 MPa, <i>f</i> 'b 72.7 MPa, <i>f</i> 's 5.3 MPa, <i>f</i> 'p 10.9 MPa Edge 190: E 14384 MPa, <i>f</i> 'b 72.0 MPa, <i>f</i> 's 5.2 MPa, <i>f</i> 'p 10.9 MPa Edge 290: E 15553 MPa, <i>f</i> 'b 68.7 MPa, <i>f</i> 's 5.2 MPa, <i>f</i> 'p 10.9 MPa Flat: E 14741 MPa, <i>f</i> 'b 67.8 MPa, <i>f</i> 's 5.3 MPa, <i>f</i> 'p 8.7 MPa Axial: <i>f</i> 't 35.8 MPa, <i>f</i> 'c 41.8 MPa F17 A-Bond E ₀ H2s 59
240/300 x 63 LVL E16 F22	01/08/2022	240/300 x 63 Larch Laminated Veneer Lumber for General Beams used on edge only Edge 240: E 16543 MPa, <i>f</i> 'b 69.7 MPa, <i>f</i> 's 5.8 MPa, <i>f</i> 'p 10.8 MPa Edge 300: E 17231 MPa, <i>f</i> 'b 82.6 MPa, <i>f</i> 's 5.3 MPa, <i>f</i> 'p 10.8 MPa F22 A-Bond E ₀ H2s 59

BMP 713299
11/08/2022 Page 3 of 3



...making excellence a habit.